


# Smoke and Dye Testing Summary

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-211	Smoke	8/4/2009	ADS/TM	S17A_019MH	Dry	Yes	475.41



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

---

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-211	Smoke	8/4/2009	ADS/TM	S17A__019MH	Dry	Yes	475.41

### Isolated Pipes

---

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S17A__022G1	S17A__022DE	S17A__019MH	149.312	8
S17A__019G1	S17A__019MH	S17A__005MH	326.094	8

### Observations & Photos

---

**Obs\_ID** S1028-211-OB01

**Address** 653 Bentalou St.

**Status** Private

**Source** Cleanout

**Location** Yard - front

**Nearest MH** S17A\_\_019MH

**Comments** Smoke from cleanout in front yard. 653 Bentalou St.



**Picture** \S1028-211-OB01-P01.jpg

**Comments** Front of house, 653 Bentalou St.